


NOTES:-

1. DIODES D2 AND D3 ARE ONLY FITTED ON LATER ISSUES OF CONVERTER, RINGING No.9A MARK 2.
2. CAPACITOR C2 IS NOT FITTED ON EARLIER ISSUES OF CONVERTER, RINGING. IF INTERFERENCE FROM A POWERFUL RADIO TRANSMITTER IS EXPERIENCED ON INSTALLATIONS WHERE THIS CAPACITOR HAS NOT BEEN PROVIDED BY THE MANUFACTURER, CAPACITOR No.8017B, 0.1 μ F 250V, SHOULD BE REQUISITIONED AND FITTED.



PO TELECOMMS HQRS			
PAPER : W			
DISTN :-			
GENERAL			
ISSUE			
C	NEW FORMAT, NOTES 1 & 2, DIODES D2 & D3, & CAPACITOR C2 ADDED.	TD 7.1.1	30-1-75
B	NEW FORMAT, VT1 & 2 WERE CV 7074. DI WAS CV 448 S.A.H.W		6-11-67