


# AUTOMATIC SYSTEM

## TELEPHONE N° 82

N.182<sup>A</sup> 9.8.21.  
A.T. 500<sup>G</sup>

BELL SET N°1.

TELEPHONE N°82 (MARK 234.)



Note - A direct current through bell coils with positive on terminal E should pull armature against bias spring.